OUT 52391

S	E	C	R	F	Т	292	1 1	137
~		•	31	Ľ	1	636	1 1	DZ.

В.

2	5	X	1

1. CAMERA B 8 WAS USED IN MISSION 3782 FLOWN ON 26 NOVEMBER 2 DEC 1963
1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

9R SIDE: FILM METERING IS SLIGHTLY ERRATIC THROUGHOUT THE

HFS __

002

2. ORIGINAL NEGATIVE:

CJS

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

CFC ____

MISSION. THE DATA CHAMBER IS CONSISTENTLY CUT OFF AT THE INBOARD

PNS ____

(UNTITLED) EDGE, RESULTING IN PARTIAL LOSS OF THE CLOCK FACE.

ACL ____

THIS MAY BE DUE TO SLIGHT MISTRACKING OF THE FILM. PROCESSING

Grace (File)

STREAKS ARE PRESENT, HEAD TO TAIL. OF THESE, THE MOST APPARENT

ONE IS A CONTINUOUS STREAK LOCATED 3.40" FROM, AND PARALLEL TO,

THE OUTBOARD EDGE OF THE FILM. HEAT SPLICES ARE PRESENT WITHIN

THE FORMATS OF FRAMES 685 AND 1416. FRAMES 522-524 ARE SEVERELY

DAMAGED BY NUMEROUS TEARS AND EMULSION LIFTS, PROBABLY DERIVED

FROM LIQUID MATTER WHICH SPLASHED ONTO THE MATERIAL AFTER DEVELOP-

MENT WAS COMPLETED. FRAMES 11-292 CONTAIN MINUS DENSITY SPOTS

WHICH VARY IN NUMBER AND ARRAY BUT ALL ARE LOCATED WITHIN INCHES

OF THE INBOARD EDGE. A SINGLE MINUS-DENSITY SPOT, LOCATED 1.85"

FROM THE INBOARD EDGE AND ALIGNED WITH FRAME-CENTER IS PRESENT

THROUGHOUT FRAMES 293-1488. THE SPOT SHIFTS TO WITHIN 0.75"

OF THE TAKE-UP EDGE IN FRAMES 1489-1511, AND FRAMES 1586-1596.

NO MINUS-DENSITY SPOTS ARE DETECTED IN FRAMES 1512-1585. THEIR

LAST APPEARANCE IS IN FRAMES 1597-1603, WHERE A ROW OF SPOTS ARE

ARRAYED APPROXIMATELY Ø.25" FROM THE INBOARD EDGE.

Declassification Review by NGA/DoD

GROUP 1
Excluded from automatic
downgrading and
declassification

- C. 9L SIDE: THERE IS A REFLECTION FROM THE FORMAT FRAME ALONG
 THE OUTBOARD OF THE FORMAT THROUGHOUT THE MISSION. PROCESSOR
 INDUCED STREAKS ARE PRESENT IN THE FIRST 682 FRAMES WHERE THEY
 TERMINATE AT A HEAT SPLICE. HEAT SPLICES ARE NOTED IN FRAMES 682
 AND 1370 AND A MANUFACTURER'S SPLICE IS NOTED IN FRAME 1214.
 THERE ARE BLISTERS IN FRAMES 1153, 1554, AND 1627 THROUGH 1630.
 CRIMPS, CAUSED BY IMPROPER HANDLING, ARE NOTED IN MOST FRAMES THAT
 ARE AFFIXED TO LEADERS AND TRAILERS (IDENTS). EXAMPLES WOULD INCLUDE
 FRAMES 932, 1065, 1198, 1331, 1597, 1863, 1995 AND 2128.
- D. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES OTHER THAN THOSE NOTED ABOVE. THE FIRST FRAME IS TITLED 005 AND THE LAST FRAME IS TITLED 2139.
 - 3. POSITIVE:
- A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE POSITIVES ARE GOOD.
- B. CLOUDS COVER APPROXIMATELY 30 PERCENT OF THE MISSION. SECRET

END OF MESSAGE